

## SITE INSPECTION PRIORITIZATION (SIP), REGION X

- EPA WAM - Deborah Flood
- URS SM - Libby Goldstein/Kara Steward (acting)

The WA consists of the following tasks:

1. Provide General Work Assignment Management
2. Conduct Site-specific Site Inspection Prioritization

### Focus This Semester:

- Complete the Level 3 SIP sites assigned.
- Evaluate and modify graphics costs as appropriate.
- EPA needs to assign the balance of the SIP sites to fill the work assignment.

TOTAL FUNDS REC'D	% OF TOTAL INC'D	APP'D BUDGET(S)		EXP. LIMIT AND FUNDS EXHAUST				COSTS WITH FEE	
		\$	LOE	\$	LOE	75% EXH.	% INC'D	INVOICED 12/25/92	EST. INC'D 12/25/92
309	15%	309	4,192	150	1,035	11/13/92	32%	46	47

Dollars in thousands

### A. Activities during this invoice period included:

- The draft field sampling plan for the Oeser Cedar Level III SIP site was submitted to the EPA SAM on 12/04/92.
- A follow-up meeting was conducted with the EPA SAM concerning the Oeser Cedar Field Sampling Plan. At this meeting, the field sampling was put on hold, to be scheduled to start after the winter season has ended.
- The recommendations memorandum for the Most Western Laundry Level III SIP site was submitted to the EPA SAM on 12/10/92.
- OCIs were completed for assigned SIP sites: Lane Co. Landfill (Short Mountain), Weyerhaeuser, Georgia Pacific, Mulkey's, Southern Pacific, JH Baxter, Union Carbide, Lane Co. Landfill (Willamette).

### B. Activities planned for the next invoice period include:

- Conduct site visit of Day Island and Short Mountain Landfills, which are both Level III SIPs.

- Initiate work on assigned Level I SIPs.
- Submit final Oeser Cedar Level III SIP Field Sampling Plan.
- Complete Most Western Laundry Level III SIP work assignment upon receipt of EPA direction.

C. Problems and Recommended Solutions:

- None.